



INDIAN INSTITUTE OF TECHNOLOGY BOMBAY
MATERIALS MANAGEMENT DIVISION
Powai, Mumbai 400076.

Ref. PR No. 1000054525

Rfq. No. 3600003039

Item Description : Repair of Vicon Motion Capture Cameras Mode Vantage V5 (Qty - 02 No.s)

Sr. No	Item Description	Technical Compliance (Yes / No)	Additional Information (if any)
1.	Repair of Vicon Motion Capture Cameras Mode Vantage V5 (Serial No.s V5-VS-5259 & V5-VS-5260) (Qty - 02 Nos)		